Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

TOP SECRET

PHOTOGRAPHIC INTERPRETATION REPORT

NYANDOMA SENSITIVE OPERATIONS COMPLEX USSR OCTOBER 1965

25X1

OCTOBER 1965

COPY 27

4 PAGES

25X1

GROUP 1 EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION

TOP SECRET

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

25X1
Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

Page Denied

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

25X1

NYANDOMA SENSITIVE OPERATIONS COMPLEX, USSR
OCTOBER 1965

This report updates March 1965 information 1/ on the Nyandoma Sensitive Operations Complex, which is approximately 4 nautical miles (nm) south of Nyandoma, USSR, at 61-36N 40-20E (Figure 1). In October 1965, approximately 85 percent of the complex was obscured by heavy clouds and dense cloud shadows. The photographic coverage of the clear portion of the complex is excellent. Only the military housing facilities and the construction workers housing are clearly visible. The Rail Facility and the motor pool are obscured by a dense cloud shadow.

In the military housing facilities, 4 new 3-story barracks identical to the existing 5 have been constructed (Figure 2). A foundation for a tenth barracks is under construction north-northwest of the H-shaped messhall. A second U-shaped probable headquarters building has been constructed east-northeast of the existing U-shaped administration building. The ground between the new building and the barracks has been landscaped. An unidentified building approximately 115 by 95 feet is under construction at the northwest end of the landscaped grounds.

Although vehicles were observed in the motor pool, they could not be identified (Figure 2). Rolling stock observed in the Rail Facility could not be identified. The loop road serving the traveling bridge crane has been completed and paved. Three FAGOT aircraft and 2 possible aircraft fuselages are parked in a cleared area near the northwest end of the loop road. In April 1964, 3 FAGOT aircraft were parked on a hardstand at this site.

25X1

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6



FIGURE 1. LOCATION MAP

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

FIGURE 2. SUPPORT FACILITIES IN THE WESTERN PORTION OF THE COMPLEX, OCTOBER 1965.

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

25X1

REFERENCES

25X1

DOCUMENT

1. NPIC, *Sensitive Operations Complexes, USSR*, Jul 65 (TOP SECRET CHESS RUFF CODEWORD) 25X1

REQUIREMENT

CIA, C-DI5-83,030

NPIC PROJECT

11251/66 (partial answer)

25X1

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6

Sanitized Copy Approved for Release 2011/06/28 : CIA-RDP78T04759A002000010045-6